



Bolts at Bottom A pillar

p2 of 8
Rev 2 ✓



Machine Screws at Bottom A pillar



WOOD MOUNTING OF "B" pillar casting

